Sunday, September 4, 2011

No work on site

Monday, September 5, 2011

Labor Day, No Work Scheduled

Tuesday, September 6, 2011

Work Schedule:
0415 Depart Hotel
0525 Arrive Desert Center
0530 Morning Safety Brief
0600 Drive to work site
0610 Arrive Solar Site commence operations (No construction activities allowed by order of BLM)
1100-1130 field lunch
1130 resume operations
1420 Clearance from the BLM to continue construction
1500 Malko attended production Meeting
1555 Production meeting ends
1600 Depart Desert Center
1715 Arrive hotel
1725-1800 Time Card, reports, admin,

Comments:
- Clearance from the BLM to continue construction of the Desert Sunlight Solar Farm was received at 1420 today.
- UXO Support consisted of walking with the biologist monitoring team over Area 1A and searching for signs of MEC or UXO. Cliff was asked to Identify a suspect cone shaped object, it was part of a fishing reel.
- No MEC or UXO found

Weather: Low temperature today was 82 F, High temperature today was +102 F.

Wednesday, September 7, 2011

Work Schedule
0415 Depart Hotel
0525 Arrive Desert Center
0530 Morning Safety Brief
0600 Shuttle bus to work site
0610 Arrive Solar Site commence operations
1100-1130 field lunch
1130 resume operations
1500 Malko attended production Meeting
1555 Production meeting ends

1600 Depart Desert Center
1715 Arrive hotel
1725-1800 Time Card, reports, admin,

Comments:
- UXO Support consisted of monitoring excavation of a kit fox burrow by the biologist team and the back fill of the turtle fence excavation
- Client plans on working Saturdays and Sundays for the next two weeks. We will possibly be working up to 84 hours in one week.
- No MEC or UXO found

Weather: Low temperature today was 82 F, High temperature today was +107 F.

Thursday, September 8, 2011

Work Schedule:
0425 Depart Hotel
0528 Arrive Desert Center
0530 Morning Safety Brief
0600 Shuttle bus to work site
0610 Arrive Solar Site commence operations
1100-1130 field lunch
1130 resume operations
1500 Malko attended production Meeting
1610 Production meeting ends
1615 Depart Desert Center
1725 Arrive hotel
1725-1800 Time Card, reports, admin,

Comments:
- UXO Support consisted of monitoring excavation of a kit fox burrow by the biologist team, monitoring construction/excavation activities in the move on area.
- No MEC or UXO found

Weather: Low temperature today was 86 F, High temperature today was 113 F.

Friday, September 9, 2011

Work Schedule:
0425 Depart Hotel
0528 Arrive Desert Center
0530 Morning Safety Brief
0600 Shuttle bus to work site
0610 Arrive Solar Site commence operations
1100-1130 field lunch
1130 resume operations
1730 Desert Center
1845 Arrive hotel

1845-1930 Time Card, reports, admin,

Comments:

- UXO Support consisted of monitoring excavation of two kit fox burrows by the biologist team, monitoring trenching for turtle fencing in area 1A, and monitoring construction/excavation activities in the move on area.
- No MEC or UXO found
- Will be working Saturday and Sunday

Weather: Low temperature today was 86 F, High temperature today was 102 F.

Saturday, September 10, 2011

Work Schedule

0415 Depart Hotel
0520 Arrive Desert Center
0530 Morning Safety Brief
0600 Shuttle bus to work site
0610 Arrive Solar Site commence operations
1100-1130 field lunch
1130 resume operations
1730 Depart Desert Center
1845 Arrive hotel
1845-1915 Time Card, reports, admin

Comments:

- UXO Support consisted of monitoring excavation of two kit fox burrows by the biologist team and monitoring construction/excavation activities in the move on area.
- Work day is planned to be 11 – 12 hours per day for the next week at a minimum
- No MEC or UXO found

Weather: Low temperature today was 69 F, High temperature today was 102 F