

DEPARTMENT OF AIR QUALITY AND ENVIRONMENTAL MANAGEMENT

DUST CONTROL MONITOR RECORD OF DAILY DUST CONTROL INSPECTIONS AND ACTIONS

Project Name: DESERT SUNLIGHT

Date: 9-19-11

Completed By: JOSE L. MERLAN

Record daily inspection results and corrective measures for dust control below.

Daily:

Dust Sign No Dust Control Permit No Weather Forecast 100° H

Time	Temp, Wind Speed & Dir	Soil Condition	Method 9 Opacity %	Track Out Condition NO TRACK OUT	Notes, Action Taken 7AM-8AM MONITORED AGGREGATE NO TRACK OUT. AVERAGE OPACITY 5.1%
7,00111	73°F, .3mph NORTH	MoisT	2%, 10%, 10%	VISIBLE NO TRACK OUT	8AM-9AM MONITORED AGGREGATE and Busing
8-9AM	81°F, 7mph NE	MOIST	15%, (SCRAPER)	MISIBLE	4 water truck operating. 9 AM-10 AM MONITORED AGGREGATE 4 8US IN
9-10AM	NORTH	12 - 111	15% (DISKER), 20%, * 10%, *45%.		9AM-10AM MONITORED BANCE UNTIL WATER ARRESTED GROUND DISTURBANCE UNTIL WATER ARRESTED TO-11AM MONITORED AGAREGATE, 10-11AM MONITORED AGAREGATE, 10-11AM MONITORED AGAREGATE, 20ER 15 Mps were creating exercise of the super creating exercise of the super creating exercise.
C - 11 0 00 1	SW,			track out &	DUER 15 MPG Were Creating
1AM-12PM	93°F, .Imph	Moist	5%, 2%.	x18 feet	*- HAS BUSING WASH OFF THE TRACK OUT
1PM-ZPM	101° E , -2mph	MoisT	21. 10		DUST DIMMES EXCEEDING 100 feet.
2PM-3PM	101°F, .3mph	MOIST	17%,	6 feet	STOPPED WORK
3PM - 4PM	100°F, .3mph	MOIST	15%., 2%	12 feet	HAD BUSING WASH OUT THE TRACK OUT.
UDM_SDM	92°F, 4mph	MOIST	18%, 3%	18 feet	ths beyond project completion and made available

This record must be maintained on site for 1 year or, in the Permittee's files for 6 months beyond project completion and made available for inspection upon demand of MDAQMD personnel.